## **BUILDING-STRUCTURE INVENTORY FORM**


DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY	
UNIQUE SITE NO. 03-05-04-78 - 4	3
SERIES	
NEG. NO	

RΔ	71
DA.	/ *

green/yello

YOUR NAME:	DATE: <b>November 15, 1979</b>
Town Hall	
YOUR ADDRESS: 655 Main St., Islip	TELEPHONE: 516 224-5450
ORGANIZATION (if any): Dept. of Plant	ning and Development
* * * * * * * * * * * * * * * * * * * *	: * * * * * * * * * * * * * * *
IDENTIFICATION	
1. BUILDING NAME (S): Purdy house (one	<del>section)</del>
2. COUNTY: Suffolk TOWN/CITY: 1	Islip VILLAGE: Bayport
3. STREET LOCATION: 94 Connetquot Avere	16
4. OWNERSHIP: a public  b. private 🛚	
5. PRESENT OWNER: Gustave Atten	ADDRESS: 94 Connetquot Ave., Bayport
6. USE: Original: residence P	Present: residence
	om public road: Yes 🛣 No 🗆
	: Explain <u>by appointment</u>
DESCRIPTION	
	c. brick d. board and batten
MATERIAL: e. cobblestone  f. shingles	X g. stucco L. other:
9. STRUCTURAL a. wood frame with interlocking	
SYSTEM: b. wood frame with light memb	
(if known) c. masonry load bearing walls	
d. metal (explain)	
e. other	Cata Data State Control D
11. INTEGRITY: a. original site b. moved X	
c. list major alterations and dates (if	known):
New windows.	
The state of the s	
12. PHOTO: ELW VI, # 17	13. MAP:Bowe, Albertson Sewer Map, Baypo
from SE, front & E.side	N



13. MAP: Bowe, Albertson Sewer Map, Bayport Q16

-3140

Residential.

14.	THREATS TO BUILDING: a. none known b. zoning c. roads d. developers c. deterioration	
	f. other:	
16.	SURROUNDINGS OF THE BUILDING (check more than one if necessary):  a. open land  b. woodland  c. scattered buildings  d. densely built-up  e. commercial  f. industrial  g. residential  x  h. other:	
17.	INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: (Indicate if building or structure is in an historic district)	
	This house is located in Bayport south of Middle Road.	
18.	OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):	
	The architecture of these houses as they are today is not pre-1873.	
SIG	It may be that a pre-1873 house was enlarged and embellished by the Smiths after 1873 and probably before 1888.  Please see also BA 70 and BA 76.  NIFICANCE	
<b>SIG</b> 19.	Smiths after 1873 and probably before 1888.  Please see also BA 70 and BA 76.  NIFICANCE  before 1873*	,
	Smiths after 1873 and probably before 1888. Please see also BA 70 and BA 76.	
	Smiths after 1873 and probably before 1888.  Please see also BA 70 and BA 76.  NIFICANCE  DATE OF INITIAL CONSTRUCTION: before 1873*	
	Smiths after 1873 and probably before 1888.  Please see also BA 70 and BA 76.  NIFICANCE  DATE OF INITIAL CONSTRUCTION: before 1873*  ARCHITECT: BUILDER: BUILDER:	1
19.	Smiths after 1873 and probably before 1888.  Please see also BA 70 and BA 76.  NIFICANCE  DATE OF INITIAL CONSTRUCTION:	
20.	Smiths after 1873 and probably before 1888.  Please see also BA 70 and BA 76.  NIFICANCE  DATE OF INITIAL CONSTRUCTION:	lir