
FOR OFFICE USE ONLY BUILDING-STRUCTURE INVENTORY FORM UNIQUE SITE NO/0305,000818 BP 4 DIVISION FOR HISTORIC PRESERVATION OUAD__ NEW YORK STATE PARKS AND RECREATION SERIES ____ ALBANY, NEW YORK (518) 474-0479 NEG. NO. ___ demolished _____ DATE: ____April 1990 Town of Islip/SPLIA YOUR NAME: __ 1991 Town Hall, 655 Main St. YOUR ADDRESS: Islip, L.I., N.Y. 11751 TELEPHONE: 516.224.5450 ORGANIZATION (if any): Dept. of Planning, Housing, and Development IDENTIFICATION W. Stone Greenhouses 1. BUILDING NAME(S): 2. COUNTY: Suffolk TOWN/CITY: Islip VILLAGE: Bayport 3. STREET LOCATION: Gillette Ave., east side, south of Mntk. Hwy. opp. Pine St. 3. STREET LOCATION: ____ 4. OWNERSHIP: a. public . b. private E 5. PRESENT OWNER: C. Luff __ ADDRESS:__ 6. USE: Original: residence & greenhouses Present: residence and greenhouses Exterior visible from public road. Yes 🔊 No 🗆 7. ACCESSIBILITY TO PUBLIC: Interior accessible: Explain partial, by app't. DESCRIPTION a. clapboard □ b. stone □ c. brick □ d. board and batten □ e. cobblestone □ f. shingles ₺ g. stucco □ other: glass and metal 8. BUILDING MATERIAL: residence 9. STRUCTURAL a. wood frame with interlocking joints b. wood frame with light members x residence SYSTEM: (if known) c. masonry load bearing walls d. metal (explain) <u>metal and glass greenhouses</u> a. excellent 🕱 b. good 🗌 c. fair 🔲 d. deteriorated 10. CONDITION: a. original site X b. moved I if so, when? 11. INTEGRITY: c. list major alterations and dates (if known): House I demolished Nov. 1991 Rest of nange demolished September 1992 Neg. KK XXII-17, fm. NW 13. MAP: NYS DOT composite Patchogue & 12. PHOTO: Sayville Quads





	그녀, 그렇게 하는데 지난 이번 이번 바람은 어린 하는데 얼마를 하게 되었다. 아래를 하게 되었다면 하는데 하는데 하는데 얼마를 하는데 되었다. 그는데 그는데 아니는데 그는데 그는데 그렇게 되었다.
14.	d. developers E e. deterioration □
	f. other: property has been subdivided
15.	RELATED OUTBUILDINGS AND PROPERTY: a. barn b. carriage house c. garage d. d. privy e. shed f. greenhouse g. shop h. gardens d. e. shop h. gardens d. e. shop d. h. gardens d. e. shop d. e
	j. other:
16.	SURROUNDINGS OF THE BUILDING (check more than one if necessary): a. open land b. woodland c. scattered buildings c. scattered buildings e. commercial f. industrial g. residential h. other: additional greenhouse business to the south
17.	INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: (Indicate if building or structure is in an historic district)
	The residences and greenhouses (4) line the east side of Gillette Avenue south of the Montauk Highway. The buildings are grouped close to the street line that is marked by large trees.
18.	OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
	The residence is a small, 1½ story, shingled, Arts & Crafts style bungalow with a projecting pedimented porch that contains short columns on a "knee-high" base wall.
SIG	NIFICANCE
19.	DATE OF INITIAL CONSTRUCTION: Greenhouses - 1927, 1928, 1929, 1931 Manuf by Hychings & Ce, Elizabeth, N.J.
	ARCHITECT:
	BUILDER:
20.	HISTORICAL AND ARCHITECTURAL IMPORTANCE:
	There is a grave concern in Bayport about "the possible destruction of several large greenhouses on Gillette Avenue to make room for residential development. The L.I. Business News reports a resurgence of the floricultu business on Long Island and its growth prospects in the 1990's. It is a shame to lose an indigenous Bayport industry."
*	SOURCES: Bayport Heritage Assoc., <u>Heritage</u> , June 1990. Interview, owner Luff. 4/ 1990.

22. THEME. Research by Society for the Preservation of Long Island Antiquities - KEK



Neg. KK XXII-16, fm. S/SW, showing row of greenhouses. Construction dates are, from south to north, 1929, 1928, 1927, and 1931. The house is located between the first and second greenhouses from the north.



Neg. KK XXII-18, fm. W/NW, showing northernmost greenhouse built in 1931.