
BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION ALBANY, NEW YORK (518) 474-0479


FOR C	OFFICE (JSE ONL	Υ	
	163			×-0-
UNIQU	JE SITE	NO. <u>/03</u>	05,00	017
QUAD			200	
SERIE	S	1.1		
NEG. 1	NO			
1.5		1. 49/21/AV(0.45)	distribution of	

ALDA(VI, (VLW TORK (316) 474-0479	NEG. NO.
	LIA DATE: <u>March 1990</u>
Town Hall, 655 M	ain St. / 🔭
YOUR ADDRESS: Islip, L.I., N.Y	. 11751 TELEPHONE: 516.224.5450
ORGANIZATION (if any): Dept. of	Planning, Housing, and Development
* * * * * * * * * * * * * * * * * * * *	
IDENTIFICATION	
I. BUILDING NAME(S): Cerny Bak	ery
2. COUNTY: Suffolk TOWN/CI 3. STREET LOCATION: 1165 Smit	TY: Islip VILLAGE: Bohemia
3. STREET LOCATION: 1165 Smit	htown Ave.
4. OWNERSHIP: a. public b. private	
5 PRESENT OWNER: J.T. Maroney	ADDRESS:
	Present: <u>bakery/store/residence</u>
7. ACCESSIBILITY TO PUBLIC: Exterior v	
DESCRIPTION	
	tone C c. brick 4. board and batten chingles g. stucco cother:
9 STRUCTURAL a. wood frame with into	erlocking joints 🖸
SYSTEM: b. wood frame with light	다이들은 것은 경영점 에 가입되는 것은 것은 것이다. 그래요한 중에 보면 없는 것은 것이다. 그리고 있다. 그리고
(if known) c. masonry load bearing	
d. metal (explain)	"마른에 말하는 소리 뭐가요? 그렇다는 아무리 살아왔다면 하면 가게 되었습니까? 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그
e. other	
10. CONDITION: a. excellent 🗷 b. good 🗆	c. fair d. deteriorated
11. INTEGRITY: a. original site 🗷 b. mo	
c. list major alterations and d	
이 그 그리는 이 가는 사람이 아픈 생각이 나가 되면 가는 것이 되었다.	



13. MAP: NYS DOT Patchogue Quad






14. THREATS TO BUILDING: a, none known ☑ d. developers ☐	e. deterioration 🗌
f. other:	
a. barn □ b. carr d. privy □ e. shed g. shop □ h. gard	lage house □ c. garage ☑ □ f. greenhouse □ lens □
j, other:	
16. SURROUNDINGS OF THE BUILDING (check a. open land \(\square\) c. scattered buildings \(\lambda\) d. densely built-up \(\square\) f. industrial \(\square\) g. r. h. other:	more than one if necessary): D. woodland □ e. commercial □ esidential ☑
17. INTERRELATIONSHIP OF BUILDING AND SURI (Indicate if building or structure is in an historic dis	ROUNDINGS: itrict)
The Cerny Bakery is located on the eather the sidewalk line in a residential arprimarily during the late 19th and eather the sidewalk line is a second control of the late 19th and eather the 19th and eather 19th and eath	Paint detached houses assure a
18. OTHER NOTABLE FEATURES OF BUILDING AN	D SITE (including interior features if known):
The Cerny Bakery is a 2½ story, recta with paired windows on the principle window occupying the north bay. A sma entrance bay. A brick, 1½ story, rect baking rooms and oven (Negs. KK XIX-1 SIGNIFICANCE	ngular, gable roof, brick building (west) facade and a large store from 11 shed roof porch covers the center
19. DATE OF INITIAL CONSTRUCTION: 192	7, enlarged 1935
ARCHITECT:	
BUILDER:	
20. HISTORICAL AND ARCHITECTURAL IMPORTAN	CE:
Joseph Cerny, a baker who had graduate School for bakers in Bohemia, bought to 1927 and built this bakery. The rear w	his property from Adoloh Wali
* Rencove is in what is presently the	Republic of Czechoslovakia.
21. SOURCES:	
Interview, Mr. and Mrs. James T. Maron	ey, April 1990.
22. THE ME :	
Research by Society for the Preservati	on of Long Island Antiquities - KEK



Neg. KK XIX-19, fm. E/NE, view of baking rooms in east wing.



Neg. KK XIX-20, view of original white glazed brick oven made by A. Simon & Son, Brooklyn, N.Y.