BO 12

BUILDING-STRUCTURE INVENTORY FORM


DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION ALBANY NEW YORK (518) 474-0479


FOR (OFFICE USE	ONLY	
UNIO	UE SITE NO	10305.0	20800
OUAE			
SERIE	A TENNE STREET, STREET		
NEG.	SECURITY OF THE SECURITY		
TILO.	110: 	The state of the s	

ILW TORK STATE FARKS AND RECKEATION	I SERIES
ALBANY, NEW YORK (518) 474-0479	NEG. NO
YOUR NAME: Town of Islip/SPLIA	DATE: March 1990
Town Hall, 655 Main YOUR ADDRESS: Islip, L.I., N.Y.	
ORGANIZATION (if any): Dept. of Pla	nning, Housing, and Development
	* * * * * * * * * * * * * * * * * * * *
IDENTIFICATION Union Ha	111 (The Dove Apartments)
COUNTY: Suffolk TOWN/CITY:	Islip VILLAGE: Bohemia
3. STREET LOCATION: 944 Unic 4. OWNERSHIP: a. public b. private 3)11 St.
5 PRESENT OWNER:	ADDRESS:
5. PRESENT OWNER: 6. USE: Original: meeting hall 7. ACCESSIBILITY TO PUBLIC: Exterior visible Interior access	Present: <u>apartment house</u> le from public road: Yes 😾 No 🗆 ssible: Explain <u>private residences</u>
DESCRIPTION	
8. BUILDING a. clapboard □ b. stone MATERIAL: e. cobblestone □ f. shing	e
9. STRUCTURAL a. wood frame with interloc SYSTEM: b. wood frame with light r	cking joints members
내용 교회의 그 집에서 아들이 있고 아픈 전에 전하고 있는 이번 경험을 받아 있다. 그런 그 집에 가는 경험을 받는 것은 아니라 가장 그 그리고 있다.	
(if known) c. masonry load bearing wa d. metal (explain)	
e. other	c. fair \(\text{d. deteriorated } \text{\text{\$\square}} \) \(\text{X} \) if so, when? \(\text{c. 1910} \)
Moved from the corner	facing Smithtown Avenue and extend


12. PHOTO: Neg. KK XXI-22, fm NW

13. MAP: NYS DOT Patchogue Quad





14	THREATS TO BUILDING: a. none known 図 b. zoning □ c. roads □ d. developers □ e. deterioration □
. 1004 . 3	하나 4 2 2 4 5 2 5 5 5 6 5 5 5 5 5 5 5 5 5 5 5 5 5 5
15.	RELATED OUTBUILDINGS AND PROPERTY: a. barn b. carriage house c. garage c.
	g. snop \ n. gardens \
16.	j. other: SURROUNDINGS OF THE BUILDING (check more than one if necessary): a. open land b. woodland c. scattered buildings d. densely built-up e. commercial f. industrial g. residential h. other:
17.	INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: (Indicate if building or structure is in an historic district)
18.	Union Hall is located on the south side of Union Street near the SW corner of Smithtown Avenue. The building, set close to and perpendicular to the street, is surrounded by detached residences of varying age from the early to mid 20th century. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
	Union Hall is a large, rectangular, $2\frac{1}{2}$ story building with a low gable roof. The building is set on a rusticated concrete block foundation, including the two story extension on the principle (north) facade that contains a center entrance under a pedimented porch surrounded with wood lattice.
SIGN	NIFICANCE
	DATE OF INITIAL CONSTRUCTION: 1892
	ARCHITECT:
	BUILDER:
20.	HISTORICAL AND ARCHITECTURAL IMPORTANCE:
	All entertainments and public dances, meetings, etc. took place in Union Hall from 1872 until 1920 when it was sold for the purpose of making cigars. Cigar making had been a prime source of work here since 1876.
	Today the building serves as an apartment house.
1. <u>I</u>	SOURCES: History of Bohemia, 1985, pp. 11 & 46-47.
'2.]	THEME: Research by Society for the Preservation of Long Island Antiquities - KEK



View towards south along Smithtown Avenue with Union Hall at the right. Photograph pre-1909. Korten photograph, Coll. Nassau County Museum Library