

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. 10305.000887

QUAD _____

SERIES _____

NEG. NO. _____

Form 12

YOUR NAME: B. Van Liew, Consultant/WHC DATE: 5/7/83

YOUR ADDRESS: Box 416, St. James, L.I. 11780 TELEPHONE: 516-584-5600

ORGANIZATION (if any): _____

IDENTIFICATION

- 1. BUILDING NAME(S): Building 93-Home 5
- 2. COUNTY: Suffolk TOWN/CITY: Islip VILLAGE: Central Islip
- 3. STREET LOCATION: _____
- 4. OWNERSHIP: a. public b. private
- 5. PRESENT OWNER: New York State ADDRESS: _____
- 6. USE: Original: _____ Present: employee residence
- 7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes No
Interior accessible: Explain

DESCRIPTION


- 8. BUILDING MATERIAL: a. clapboard b. stone c. brick d. board and batten
e. cobblestone f. shingles g. stucco other: _____
- 9. STRUCTURAL SYSTEM: a. wood frame with interlocking joints
(if known) b. wood frame with light members
c. masonry: load bearing walls
d. metal (explain) _____
e. other _____
- 10. CONDITION: a. excellent b. good c. fair d. deteriorated
- 11. INTEGRITY: a. original site b. moved if so, when? _____
c. list major alterations and dates (if known): _____

12. PHOTO: CI-WHC-r-1,35 from SW

13. MAP: NYS DOT-Bayshore Quad



HP-1



14. THREATS TO BUILDING: a. none known b. zoning c. roads
 d. developers e. deterioration
 f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:

- a. barn b. carriage house c. garage
 d. privy e. shed f. greenhouse
 g. shop h. gardens
 i. landscape features: _____
 j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):

- a. open land b. woodland
 c. scattered buildings
 d. densely built-up e. commercial
 f. industrial g. residential
 h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:

(Indicate if building or structure is in an historic district)

The building is located on the hospital grounds on the east side of Carleton Ave.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____ 1939-1940 _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

The building is a 3 story and high basement, hip roof, T-shaped brick structure with 3 bay, 3 story, gable roof wing on east and slightly projecting 3 story, gable roof center section for entrance on the west (front) facade. Elliptical sunbursts in gable peaks. Segmental arched entrances with copper pagoda hoods on iron lattice work, *flank main entrances.*

21. SOURCES:

Atlas of the Ocean Shore of Suffolk Co. (westerly section)
 N.Y.: E. Belcher Hyde, 1915, Plate 6

22. THEME: