

**BUILDING-STRUCTURE INVENTORY FORM**

DIVISION FOR HISTORIC PRESERVATION  
NEW YORK STATE PARKS AND RECREATION  
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY	
UNIQUE SITE NO.	<u>103-05-0593-HSP</u>
QUAD	_____
SERIES	_____
NEG. NO.	_____

H 13

YOUR NAME: B. Van Liew, Consultant /MSF DATE: 8/79  
N Sherrill Foster  
 YOUR ADDRESS: Box 416, St. James, L.I. TELEPHONE: 516-584-5600  
 ORGANIZATION (if any): Natural Heritage Trust

\*\*\*\*\*

**IDENTIFICATION**

TAYLOR ESTATE : OUTBUILDING

- BUILDING NAME(S): (Picnic Area #3 Comfort Station, Heckscher State Park.)
- COUNTY: Suffolk TOWN/CITY: Islip VILLAGE: East Islip
- STREET LOCATION: Timber Point Rd; south side
- OWNERSHIP: a. public  b. private
- PRESENT OWNER: LISPC ADDRESS: Belmont State Park
- USE: Original: part of estate complex Present: comfort station
- ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes  No   
Interior accessible: Explain Business

**DESCRIPTION**

- BUILDING MATERIAL: a. clapboard  b. stone  c. brick  d. board and batten   
e. cobblestone  f. shingles  g. stucco  other: \_\_\_\_\_
- STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints   
b. wood frame with light members   
c. masonry load bearing walls   
d. metal (explain) \_\_\_\_\_  
e. other \_\_\_\_\_
- CONDITION: a. excellent  b. good  c. fair  d. deteriorated
- INTEGRITY: a. original site  b. moved  if so, when? 1920's (?)  
c. list major alterations and dates (if known): \_\_\_\_\_

Roll 2

12. PHOTO: H 13 -18  
West side of building

13. MAP: Bay Shore East Quadrangle



AUG • 79

14. THREATS TO BUILDING: a. none known  b. zoning  c. roads   
 d. developers  e. deterioration   
 f. other: \_\_\_\_\_

15. RELATED OUTBUILDINGS AND PROPERTY:  
 a. barn  b. carriage house  c. garage   
 d. privy  e. shed  f. greenhouse   
 g. shop  h. gardens   
 i. landscape features: \_\_\_\_\_  
 j. other: Pavillion

16. SURROUNDINGS OF THE BUILDING  (check more than one if necessary):  
 a. open land  b. woodland   
 c. scattered buildings   
 d. densely built-up  e. commercial   
 f. industrial  g. residential   
 h. other: \_\_\_\_\_

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:  
 (Indicate if building or structure is in an historic district)

Situated under shade of Trees in an open area

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):  
 2 bay one story gable roof shingled building. Scalloped shingles in upper half of building.

**SIGNIFICANCE**

19. DATE OF INITIAL CONSTRUCTION: after 1885

ARCHITECT: \_\_\_\_\_

BUILDER: \_\_\_\_\_

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Part of the Taylor-Pyne complex, carrying the theme of scalloped shingles above vertical siding or clapboarding on lower areas.

21. SOURCES:

Interview with Mr. O'Neil 7/8/79

22. THEME:

