

**BUILDING-STRUCTURE INVENTORY FORM**

DIVISION FOR HISTORIC PRESERVATION  
NEW YORK STATE PARKS AND RECREATION  
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY	
UNIQUE SITE NO.	<u>103-05-0596-<sup>H</sup>16</u>
QUAD	_____
SERIES	_____
NEG. NO.	_____

YOUR NAME: B. Van Liew, Consultant/ NSF DATE: 8/79

N Sherrill Foster

YOUR ADDRESS: Box 416, St. James, L.I. TELEPHONE: 516-584-5600

ORGANIZATION (if any): Natural Heritage Trust

\*\*\*\*\*

**IDENTIFICATION**

PLUMB ESTATE: OUTBUILDING

1. BUILDING NAME(S): (Picnic Area # 6 Comfort Station Heckscher State Park.)

2. COUNTY: Suffolk TOWN/CITY: Islip VILLAGE: East Islip

3. STREET LOCATION: Timber Point Rd; south side

4. OWNERSHIP: a. public  b. private

5. PRESENT OWNER: LISPC ADDRESS: Belmont State Park

6. USE: Original: farm building Present: comfort station

7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes  No

Interior accessible: Explain business

**DESCRIPTION**

8. BUILDING MATERIAL: a. clapboard  b. stone  c. brick  d. board and batten

e. cobblestone  f. shingles  g. stucco  other: \_\_\_\_\_

9. STRUCTURAL SYSTEM: a. wood frame with interlocking joints

(if known) b. wood frame with light members

c. masonry load bearing walls

d. metal (explain) \_\_\_\_\_

e. other \_\_\_\_\_

10. CONDITION: a. excellent  b. good  c. fair  d. deteriorated

11. INTEGRITY: a. original site  b. moved  if so, when? 1932

c. list major alterations and dates (if known):

Made into a comfort station in 1932

major Remodelling.

12. PHOTO: no negative

13. MAP: Bay Shore East quadrangle

Needs  
to be  
relocated

14. THREATS TO BUILDING: a. none known  b. zoning  c. roads   
 d. developers  e. deterioration   
 f. other: \_\_\_\_\_
15. RELATED OUTBUILDINGS AND PROPERTY: a. barn  b. carriage house  c. garage   
 d. privy  e. shed  f. greenhouse   
 g. shop  h. gardens   
 i. landscape features: on edge of parking lot near playing fields  
 j. other: \_\_\_\_\_
16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):  
 a. open land  b. woodland   
 c. scattered buildings  d. densely built-up  e. commercial   
 f. industrial  g. residential   
 h. other: \_\_\_\_\_
17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:  
 (Indicate if building or structure is in an historic district)  
 Situated between open meadow area and parking lot with picnic groves on either side, and playing fields.
18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):  
 3 bay shingled one story gable roof building with very narrow verge board and fascia.

**SIGNIFICANCE**

19. DATE OF INITIAL CONSTRUCTION: \_\_\_\_\_

after 1872

ARCHITECT: \_\_\_\_\_

BUILDER: \_\_\_\_\_

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:


one of the numerous outbuildings of the Plumb estate.

*Similar in appearance to H-20 (comfort station)*

21. SOURCES: Interview with Mr. O'Neil, 7/8/79

22. THEME:

Bay Shore East Quadrangle



45100

1800

42/3

RIVER

Great River

CONNETQUOT

PARK

STATE

HECKSCHER


East Isip

per Wingunhappage

A-16 West Beach

Nicoll Pt

Town Beach



45100  
1800  
42/3  
H 16  
Bay Shore East Quadrangle  
RIVER  
Great River  
CONNETQUOT  
PARK  
STATE  
HECKSCHER  
East Isip  
per Wingunhappage  
A-16 West Beach  
Nicoll Pt  
Town Beach