

10305.000565

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. 103-05-0585-HSP
QUAD _____
SERIES _____
NEG. NO. _____

H 5

YOUR NAME: B. Van Liew, Consultant/NSF DATE: 8/79
N Sherrill Foster

YOUR ADDRESS: Box 416, St. James, L.I. TELEPHONE: 516-584-5600

ORGANIZATION (if any): Natural Heritage Trust

IDENTIFICATION

PLUMB ESTATE; RESIDENCE LI-09
(Asst. Superintendent's Cottage, Heckscher State Park) 034

- 1. BUILDING NAME(S): _____
- 2. COUNTY: Suffolk TOWN/CITY: Islip VILLAGE: East Islip
- 3. STREET LOCATION: Timber Point Rd; South Side
- 4. OWNERSHIP: a. public b. private
- 5. PRESENT OWNER: LISPC ADDRESS: Belmont State Park
- 6. USE: Original: Employee's residence Present: same
- 7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes No
Interior accessible: Explain

DESCRIPTION

- 8. BUILDING MATERIAL: a. clapboard b. stone c. brick d. board and batten
e. cobblestone f. shingles g. stucco other: _____
- 9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints
b. wood frame with light members
c. masonry load bearing walls
d. metal (explain) _____
e. other _____
- 10. CONDITION: a. excellent b. good c. fair d. deteriorated
- 11. INTEGRITY: a. original site b. moved if so, when? _____
c. list major alterations and dates (if known):
additions, 1970

Roll 2
12. PHOTO: H 5-8
South side of building

13. MAP: Bay Shore East Quadrangle



14. THREATS TO BUILDING: a. none known b. zoning c. roads
 d. developers e. deterioration
 f. other: _____
15. RELATED OUTBUILDINGS AND PROPERTY:
 a. barn b. carriage house c. garage
 d. privy e. shed f. greenhouse
 g. shop h. gardens i. landscape features: wooden fence
 j. other: _____
16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
 a. open land b. woodland
 c. scattered buildings
 d. densely built-up e. commercial
 f. industrial g. residential
 h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
 (Indicate if building or structure is in an historic district)

Building is situated on an open lawn area with several large trees shading the house which is set back from the park road

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

2½ story gable roof with extruded shaped rafter ends house with shingled second story, clapboarded first story. Wall face gable dormer, small central chimney, octagonal turret of 3 ½ stories on SW corner of house.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: after 1872

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Part of Plumb estate. A Queen Anne dwelling of charm with much of its charm still visible.

21. SOURCES: Interview with Mr. O'Neil 7/8/79.
 Interview with Betty Kuss. Old Oakdale History & South Side Signal 10/19/
 1872. 8/18/79.

22. THEME:

