
NYS OFFICE OF PARKS, RECREATION & HISTORIC PRESERVATION DIVISION FOR HISTORIC PRESERVATION (518) 237-8643

YOUR NAME: John Auwaerter DATE: 12/1996
YOUR ADDRESS:
TELEPHONE:
ORGANIZATION: _ Field Services Bureau
* * * * * * * * * * * * * * * * * * * *
<u>IDENTIFICATION</u> Bayard Cutting Arboretum State Park:
1. BUILDING NAME(S): Locust Bridge (Bird Watchers Walk)
2. COUNTY: Suffolk TOWN/CITY: Islip VILLAGE: Great River
3. STREET LOCATION: Montauk Hwy; over Connetquot Brook
4. OWNERSHIP: a. public x b. private
5. PRESENT OWNER: OPRHP ADDRESS:
6. USE: Original: Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes No
Interior accessible: Explain
Interior accessible: Explain <u>DESCRIPTION</u>
DESCRIPTION
DESCRIPTION 8. BUILDING a. clapboard b. stone c. brick d. board and batten
DESCRIPTION 8. BUILDING a. clapboard b. stone c. brick d. board and batten
<pre>DESCRIPTION 8. BUILDING a. clapboard_ b. stone_ c. brick_ d. board and batten_ MATERIAL: e. cobblestone_ f. shingle_ g. stucco_ other:</pre>
DESCRIPTION 8. BUILDING a. clapboard b. stone c. brick d. board and batten MATERIAL: e. cobblestone f. shingle g. stucco other: 9. STRUCTURAL a. wood frame with interlocking joints
<pre>DESCRIPTION 8. BUILDING a. clapboard_ b. stone_ c. brick_ d. board and batten_ MATERIAL: e. cobblestone_ f. shingle_ g. stucco_ other: 9. STRUCTURAL a. wood frame with interlocking joints SYSTEM: b. wood frame with light members (if known) c. masonry load bearing walls</pre>
<pre>DESCRIPTION 8. BUILDING a. clapboard b. stone c. brick d. board and batten MATERIAL: e. cobblestone f. shingle g. stucco other: 9. STRUCTURAL</pre>
<pre>DESCRIPTION 8. BUILDING a. clapboard_ b. stone_ c. brick_ d. board and batten_ MATERIAL: e. cobblestone_ f. shingle_ g. stucco_ other: 9. STRUCTURAL a. wood frame with interlocking joints SYSTEM: b. wood frame with light members (if known) c. masonry load bearing walls</pre>
<pre>BESCRIPTION 8. BUILDING a. clapboard b. stone c. brick d. board and batten MATERIAL: e. cobblestone f. shingle g. stucco other: 9. STRUCTURAL</pre>
DESCRIPTION 8. BUILDING a. clapboard b. stone c. brick d. board and batten MATERIAL: e. cobblestone f. shingle g. stucco other: 9. STRUCTURAL
DESCRIPTION 8. BUILDING a. clapboard b. stone c. brick d. board and batten MATERIAL: e. cobblestone f. shingle g. stucco other: 9. STRUCTURAL

12. PHOTO:

13. MAP: attached



14:	THREATS TO BUILDING: a. none known b. zoning c. roads
	d. developers e. deterioration
1 5	f. other RELATED OUTBUILDINGS AND PROPERTY:
15.	
	a. barn b. carriage house c. garage
	d. privy e. shed f. greenhouse
	g. shop h. gardens
	i. landscape features:
	j. other:
16.	SURROUNDINGS OF THE BUILDING (check more than one if necessary)
	a. open land b. woodland
	c. scattered buildings
	d. densely built-up e. commercial
	f. industrial g. residential
	h. other
17.	INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
	(indicate if building or structure is in an historic district)
	OTHER NOTABLE FEATURES OF THE BUILDING AND SITE:
18.	
18.	
18.	(include interior features if known)
18.	
18.	
	(include interior features if known)
SIG	(include interior features if known)
SIG	(include interior features if known)
SIG	(include interior features if known) NIFICANCE DATE OF CONSTRUCTION: rebuilt during park period; historic feature
SIG	(include interior features if known)
SIG	(include interior features if known) NIFICANCE DATE OF CONSTRUCTION: rebuilt during park period; historic feature ARCHITECT:
SIG	(include interior features if known) NIFICANCE DATE OF CONSTRUCTION: rebuilt during park period; historic feature
<u>sig</u>	(include interior features if known) NIFICANCE DATE OF CONSTRUCTION: rebuilt during park period; historic feature ARCHITECT: BUILDER:
<u>sig</u>	(include interior features if known) NIFICANCE DATE OF CONSTRUCTION: rebuilt during park period; historic feature ARCHITECT:
<u>sig</u>	(include interior features if known) NIFICANCE DATE OF CONSTRUCTION: rebuilt during pack period; historic feature ARCHITECT: BUILDER: HISTORICAL AND ARCHITECTURAL IMPORTANCE:
<u>sig</u>	(include interior features if known) NIFICANCE DATE OF CONSTRUCTION: rebuilt during park period; historic feature ARCHITECT: BUILDER: HISTORICAL AND ARCHITECTURAL IMPORTANCE: Existing piling/culvert structure replaced original locust-clad bridge
<u>sig</u>	(include interior features if known) NIFICANCE DATE OF CONSTRUCTION: rebuilt during pack period; historic feature ARCHITECT: BUILDER: HISTORICAL AND ARCHITECTURAL IMPORTANCE:
<u>sig</u>	(include interior features if known) NIFICANCE DATE OF CONSTRUCTION: rebuilt during park period; historic feature ARCHITECT: BUILDER: HISTORICAL AND ARCHITECTURAL IMPORTANCE: Existing piling/culvert structure replaced original locust-clad bridge
<u>sig</u>	(include interior features if known) NIFICANCE DATE OF CONSTRUCTION: rebuilt during park period; historic feature ARCHITECT: BUILDER: HISTORICAL AND ARCHITECTURAL IMPORTANCE: Existing piling/culvert structure replaced original locust-clad bridge
19. 20.	(include interior features if known) NIFICANCE DATE OF CONSTRUCTION: rebuilt during park period; historic feature ARCHITECT: BUILDER: HISTORICAL AND ARCHITECTURAL IMPORTANCE: Existing piling/culvert structure replaced original locust-clad bridge
19. 20.	(include interior features if known) NIFICANCE DATE OF CONSTRUCTION:
19. 20.	(include interior features if known) NIFICANCE DATE OF CONSTRUCTION:
19. 20.	(include interior features if known) NIFICANCE DATE OF CONSTRUCTION:
20. c.19	NIFICANCE DATE OF CONSTRUCTION: rebuilt during park period; historic feature ARCHITECT: BUILDER: HISTORICAL AND ARCHITECTURAL IMPORTANCE: Existing piling/culvert structure replaced original locust-clad bridge 970 (see historic photo). SOURCES:
20. c.19	NIFICANCE DATE OF CONSTRUCTION: Pebuilt during park period; historic feature ARCHITECT: BUILDER: HISTORICAL AND ARCHITECTURAL IMPORTANCE: Existing piling/culvert structure replaced original locust-clad bridge 970 (see historic photo). SOURCES: THEME/AREA(S) OF SIGNIFICANCE:
20. c.19	NIFICANCE DATE OF CONSTRUCTION: rebuilt during park period; historic feature architect: BUILDER: HISTORICAL AND ARCHITECTURAL IMPORTANCE: Existing piling/culvert structure replaced original locust-clad bridge 970 (see historic photo). SOURCES: THEME/AREA(S) OF SIGNIFICANCE: CRITERIA:
20. c.19	NIFICANCE DATE OF CONSTRUCTION: Rebuilt during park period; historic feature ARCHITECT: BUILDER: HISTORICAL AND ARCHITECTURAL IMPORTANCE: Existing piling/culvert structure replaced original locust-clad bridge 970 (see historic photo). SOURCES: THEME/AREA(S) OF SIGNIFICANCE:

