BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION ALBANY, NEW YORK (518) 474-0479

FOR O	FICE USE ONLY	
UNIQÚI	SITE NO. 10305,000823	
QUAD_		200
SERIES NEG. N		
INEG. IN		l

	_		/an-			W1 1000
	Town o				DATE	: March 1990
					TELEPHON	NE: 516.224.5450
ORGANIZATION (i	if anv):	Dept.	of P	lanning,	Housing,	and Development


IDENTIFICATION 1. BUILDING NAME (S);	former Camp Upton Barracks
2. COUNTY: SuffòIl	
	1022 Main St.
	ublic 🗆 b. private 🗵
5. PRESENT OWNER:	ADDRESS:
6. USE: Original:	<u>barracks</u> ADDRESS: retail store (travel agency)
7. ACCESSIBILITY TO	
	Interior accessible: Explain <u>partial</u>
DESCRIPTION	
8. BUILDING	a. clapboard b. stone c. brick d. board and batten
MATERIAL:	e. cobblestone f. shingles g. stucco other: modern vertical board and horizontal siding
9. STRUCTURAL	a. wood frame with interlocking joints [
SYSTEM:	b. wood frame with light members 🗓
(if known)	c. masonry load bearing walls
	d. metal (explain)
	e. Other
0. CONDITION: a. ex	cellent 🙀 b. good 🗌 c. fair 🗀 d. deteriorated 🗀
그 게 그 네트 이번 집에 바다 하는 이 때에 되었다면 살게 되어 되었다면 나무를 모았다고 했다.	iginal site \(\text{h moved } \(\text{k} \) if so when? c. 1920 from Camp Upton. Yaphank.


facades altered and new siding installed

c. list major alterations and dates (if known):

12. PHOTO: Neg. KK XXVI-9, fm. E

13. MAP: NYS DOT Patchogue Quad





14.	THREATS TO BUILDING: a. none known 🖾 b. zoning 🗆 c. roads 🗀 d. developers 🗀 e. deterioration 🗀 f. other:
15.	
	a. barn □ b. carriage house □ c. garage □
	d. privy □ e. shed □ f. greenhouse □
	g. shop 🗀 h. gardens 🗔
	i. landscape features:
	J. Other:
16.	SURROUNDINGS OF THE BUILDING (check more than one if necessary):
	a, open land □ b. woodland □
	c. scattered buildings 🔲
	d densely bu <u>ilt-</u> up □ e. commercial ☑
	f. industrial 🔲 g. residential 🗀
	h. other:
17.	INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: (Indicate if building or structure is in an historic district)
	1022 Main Street is located on the west side of the old Patchogue-Holbrook
	Patchogue-Holbrook Road was constructed to the cost It is seemed 11
	other commercial buildings either renovated from older structures or built
18.	other commercial buildings either renovated from older structures or built of the NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
	되었다. 맛있는 사람들은 이번 사람들은 아무리를 하면서 사람들이 되었습니다. 그는 사람들이 가지 사람들이 가지 사람들이 가지 않는데 그는 것이 없는데 그는 것이 없는데 그렇게 되었다. 나를 살아 없는데
	1022 Main Street is a rectangular, one story, gable roof building of utilitarian design. The principle facade facing Main Street has been renovated with timber elements and false butresses.
	NIFICANCE DATE OF INITIAL CONSTRUCTION: World War I ARCHITECT:
	님은 사용하다 하는 사람들은 사용하다는 이 사용하다 이 전 경험으로 있는 이 선생님은 사용하다 하는 사용하는 것이 되었다. 그는 사용하는 사용하는 사용하는 사용하는 사용하는 사용하는 사용하는 사용하
	BUILDER:
20.	HISTORICAL AND ARCHITECTURAL IMPORTANCE:
	This building was a Camp Upton barracks. It was moved by the Republican Club to be a community hall. Later from 1961 - 1979 it was the Moose Lodge.
21.	SOURCES:
J	Interview, Gertha Strand 4/1990.
22.	THEME:
₹.	desearch by Society for the Preservation of Long Island Antiquities - KEK