

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY	
UNIQUE SITE NO	<u>103-05-0316-021</u>
QUAD	_____
SERIES	_____
NEG. NO.	_____

Oa 32
green/
yellow

YOUR NAME: Town of Islip Town Hall DATE: 5/23/79
655 Main Street
 YOUR ADDRESS: Islip, N.Y. TELEPHONE: (516) 224-5450
 ORGANIZATION (if any): Department of Planning and Development

IDENTIFICATION


1. BUILDING NAME(S): Vanderbilt Sheds ^{EACH:} (The Artist Colony)
 2. COUNTY: Suffolk TOWN/CITY: Islip VILLAGE: Oakdale
 3. STREET LOCATION: 21-29 Jade Street
 4. OWNERSHIP: a. public b. private
 5. PRESENT OWNER: various ADDRESS: _____
 6. USE: Original: Sheds Present: residences, shed
 7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes No
 Interior accessible: Explain

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard b. stone c. brick d. board and batten
 e. cobblestone f. shingles g. stucco other: _____
 9. STRUCTURAL SYSTEM: a. wood frame with interlocking joints
 (if known) b. wood frame with light members
 c. masonry load bearing walls
 d. metal (explain) _____
 e. other _____
 10. CONDITION: a. excellent b. good c. fair d. deteriorated
 11. INTEGRITY: a. original site b. moved if so, when? _____
 c. list major alterations and dates (if known):
three bays have brick infill

12. PHOTO: Neg. 33, west facade
NJM-1

13. MAP: Bowe-Anderson
Composite



14. THREATS TO BUILDING: a. none known b. zoning c. roads
 d. developers e. deterioration
 f. other: _____
15. RELATED OUTBUILDINGS AND PROPERTY:
 a. barn b. carriage house c. garage
 d. privy e. shed f. greenhouse
 g. shop h. gardens
 i. landscape features: _____
 j. other: _____
16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
 a. open land b. woodland
 c. scattered buildings
 d. densely built-up e. commercial
 f. industrial g. residential
 h. other: similar buildings in farm complex
17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
 (Indicate if building or structure is in an historic district)
- A row of individually owned units on the East side of Jade Street, in the historic Artist Colony.
18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
 Seven bay shed of brick piers. Originally large wooden doors hung from piers, now only 3 pairs remain with original hardware. Remaining bays of 1 story brick piers have brick infill and gable roof dormers.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1890

ARCHITECT: _____

BUILDER: William Bason and Sons

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
 This building is part of the farm area of the Vanderbilt estate. In 1926, this area was purchased by Lucy Sawyer Pritchard Thompson and her son, William, turning it into the Artist Colony, a haven for many New York City Artists.

21. SOURCES:
 Charles P. Dickerson, A History of the Sayville Community,
 Suffolk County News, 1975.

22. THEME:
 Prepared by: Society for the Preservation of Long Island Antiquities
 Setauket, New York 11733
 Nina Monastero, Research Assistant
 May, 1979