## **BUILDING-STRUCTURE INVENTORY FORM**

DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION ALBANY, NEW YORK (518) 474-0479


FOR OFFICE USE ONLY	gr
UNIQUE SITE NO. 103-05-0308	-DZ1
QUAD	
SERIES	
NEG, NO.	


		NEG, NO.	
YOUR NAME: Town of	Islip Town Hal	1DATE:5	/22/79
YOUR ADDRESS: 655 Ma Islip ORGANIZATION (if any):	ain Street , N.Y. Department of	_TELEPHONE:	(516) 224-5450
ORGANIZATION (II any):			
	* * * * * * * * *	* * * * * *	* * * * * * * *
IDENTIFICATION			
1. BUILDING NAME(S): 61 Pro	s <del>noces Gat</del> e (Th	e Artist Co	leny)
2. COUNTY: Suffolk	TOWN/CITY: Isl	ip <sub>VILL</sub>	AGE: Oakdale
3. STREET LOCATION: 61 P	rincess Gate	a .	
4. OWNERSHIP: a. public 🗆			
		ORESS:	
5. PRESENT OWNER: 6. USE: Original:	Prese	<sub>ent:</sub> <u>residen</u>	se
7. ACCESSIBILITY TO PUBLIC:	Exterior visible from Interior accessible:	public road: Yes [	X No □
<u>DESCRIPTION</u>			(1975), 1985년 1970년 - 1일 시간 전 1985년 1975년 1841년 - 1987년 - 1985년 1987년 1987년 1987년 - 1987년 1
8. BUILDING a. clapboa	rd 🔲 b. stone 🗀	c. brick 🔼 d	. board and batten 🗆
MATERIAL: e. cobblest	one 🗌 f. shingles 🔲	g, stucco 🗀 ot	her:
9. STRUCTURAL a. wood fr	ame with interlocking joi	nts 🗀	
SYSTEM: b. wood fi	ame with light members	<b>X</b>	
(if known) c. masonry	√ load bearing walls 🔲 🗀		
d. metal (	explain)		
e. other_		<u> </u>	
0. CONDITION: a. excellent <b>x</b>	_ b. good 🗌 💹 c. fai	ir 🔲 🔀 d. deter	iorated 🗆
	🗓 b. moved 🗀		
c. list major alte	rations and dates (if kno	own):	

12. PHOTO: Neg. 28, south facade NJM-1

13. MAP:

Bowe-Anderson Composite A





green

# N	
14.	THREATS TO BUILDING: a. none known  b. zoning  c. roads  c. developers  e. deterioration  f. other:
	RELATED OUTBUILDINGS AND PROPERTY:  a. barn  b. carriage house c. garage d. d. privy e. shed f. greenhouse g. shop h. gardens d. i. landscape features:
16.	SURROUNDINGS OF THE BUILDING (check more than one if necessary):  a. open land  b. woodland  c. scattered buildings  d. densely built-up  e. commercial  f. industrial  g. residential  h. other: Similar buildings of farm complex
17.	INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: (Indicate if building or structure is in an historic district) At Tower Mews Road, opposite south end of L of West Barn, in the historic Artist Colony.
18.	OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):  1 story brick structure with segmental arches at window and door openings. Original vent survives on roof.
100	NIFICANCE DATE OF INITIAL CONSTRUCTION: 1890
19.	ARCHITECT:
	BUILDER: William Bason and Sons
20.	HISTORICAL AND ARCHITECTURAL IMPORTANCE: This building was part of the farm area of the Vanderbilt Estate. In 1926, this area was purchased by Lucy Sawyer Pritchard Thompson and her son, William, turniing it into the Artist Colony, a haven for many New York City artists.
21.	SOURCES: Charles P. Dickerson, <u>A History of the Sayville Community</u> , Suffolk County News, 1975.
22.	THEME: Prepared by: Society for the Preservation of Long Island Antiquities Setauket, New York 11733 Nina Monastero, Research Assistant May, 1979