## **BUILDING-STRUCTURE INVENTORY FORM**

DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION ALBANY, NEW YORK (518) 474-0479


FOR OFFICE USE ONLY	
127 05-1051	WAN
UNIQUE SITE NO. 103-05-036	Tucy
SERIES	
NEG. NO.	


0a 13 green yellow

ALBANY, NEW YORK (518) 474-0479	NEG. NO.
YOUR NAME: Town of Islip Town	그 회사를 하는 사람들은 사용성이 발표 內 점점 하는 바로 하는 것은 것이 되었다. 그는 그는 그는 그는 그는 그를 하는 것이다. 그는 그 가지 않는데 그는 그를 다 했다.
Oppinali Dureer	TELEPHONE:(516) 224-5450
ORGANIZATION (if any): Department o	f Planning and Development
IDENTIFICATION  1. BUILDING NAME(S): Vanderbilt Pott 2. COUNTY: Suffelk TOWN/CITY:	현실 보통 살아들 살아보는 그는 이렇게 살아 있다는 것이 되어 들어가 되었다. 그 살아 먹는 것이 되었다. 그 그 없는 것이 없는 것이다.
2. COUNTY: Suffelk TOWN/CITY:	Islip VILLAGE: Oakdale
3. STREET LOCATION: 10 Shore Drive	살물로 가를 잃었다면 하는 것이 살았다. 그 살이 그 그를 살고 있다면 하고 있다.
4. OWNERSHIP: a. public 🗆 b. private 🍱	
5. PRESENT OWNER: Gianquinto 6. USE: Original: potting plants	ADDRESS: See #5
6. USE: Original: <b>POTTLING PLANTS</b>	Present: residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible finterior accessible	rom public road: Yes 🗷 No 🗀 e: Explain
DEBOCKII 1101	그 내는 다음을 내고 보았다. 하는 사람들은 아무리는 아무리는 아무리는 아무리를 하는 것이 되었다. 그는 사람이 나는 사람들이 되었다.
8. BUILDING a. clapboard  b. stone  MATERIAL: e. cobblestone  f. shingles	c. brick 🔀 d. board and batten 🗆 g. stucco 🗆 other:
9. STRUCTURAL SYSTEM: b. wood frame with interlockin b. wood frame with light mem c. masonry load bearing walls to d. metal (explain) e. other	bers □
0. CONDITION: a excellent ☑ b. good ☐ 1. INTEGRITY: a. original site ☑ b. moved ☐ c. list major alterations and dates (if	if so, when?
Brick addition on ea	얼마나 사람들은 얼마나 하는 것으로 가지 않아 다른 생각하는 것이

12. PHOTO: Neg. 14, North facade NJM-1

13. MAP: Bowe-Anderson Composite







	_ green/yellow (
14.	THREATS TO BUILDING: a. none known  b. zoning  c. roads  c. roads  c. roads  c. developers  c. deterioration  c. roads  c. r
i i	a. barn □ b. carriage house □ c. garage □ d. privy □ e. shed □ f. greenhouse □ g. shop □ h. gardens ▼ i. landscape features: _adjacent to Connetquot River i. other:
16	SURROUNDINGS OF THE BUILDING (check more than one if necessary): a. open land  b. woodland c. scattered-buildings  c. scattered-buildings  c. scattered-buildings  c. scattered buildings  c. scattere
17.	INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: (Indicate if building or structure is in an historic district)  Located in a more secluded portion of the community, the Pottery is at the southeast end of Shore Road, near Middlesex Road. The Coal Pits and Walled Garden, both of the Vanderbilt estate, are supposedly located on the property.
18.	OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
	A 1-story brick structure with gable roof and some diamond- pane casement windows.
<b>SIG</b> 1	NIFICANCE DATE OF INITIAL CONSTRUCTION: Circa 1900
	ARCHITECT:
	BUILDER:
20.	HISTORICAL AND ARCHITECTURAL IMPORTANCE:
	This building is a part of the 900-acre estate of William K. Vanderbilt, built during the latter years of the 19th century.

- 21. SOURCES: Mrs. Gianquinto, owner, as interviewed on May 16, 1979. Merritt B. Hyde, Atlas of a Part of Suffolk County, Long Island New York, South Shore, E. Belcher Hyde, Brooklyn, N.Y. 1915.
- 22. THEME:

Prepared by: Society for the Preservation of Long Island Antiquities Setauket, New York 11733 Nina Monastero, Research Assistant May, 1979