BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION ALBANY, NEW YORK (518) 474-0479


FOR O	FFICE USE	ONLY		Maria a Maria
UNIQU	E SITE NO	10305	<u>,000850</u>)
QUAD.				-
SERIES	S			
NEG. N	10			
		A THE SALE OF THE	Selferal University &	1,774

NEG. NO.
YOUR NAME: Town of Islip/SPLIA DATE: May 1990
Town Hall, 655 Main St.
YOUR ADDRESS: Islip, L.I., N.Y. 11751 TELEPHONE: 516.224.5450
ORGANIZATION (if any): Dept. of Planning, Housing, and Development
* * * * * * * * * * * * * * * * * * * *
IDENCIFICATION
BUILDING NAME(S): W. Overton House (1992) COUNTY: Suffolk TOWN/CITY: Islip VILLAGE: Sayville STREET LOCATION: 35 Overton St.
2 COUNTY: Suffolk TOWN/CITY: Islip VILLAGE: Savville
2 STREET LOCATION: 35 Overton St.
4. OWNERSHIP: a. public \(\subseteq \) b. private \(\subseteq \)
F. OWNERSTITE A. PUBLIC L. I. L. PRIVATE EL.
S. PRESENT OWNER: ADDRESS: residence Present: residence
6. USE: Unginal:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road. Yes No
Interior accessible: Explain <u>private residence</u>
<u>DESCRIPTION</u>
8. BUILDING a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ MATERIAL: e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
MATERIAL: e. cobblestone [] f. shingles [] g. stucco [] other:
9. STRUCTURAL a. wood frame with interlocking joints X
SYSTEM: b. wood frame with light members
(if known) c. masonry load bearing walls 🗌 :
d. metal (explain)
e. other
10. CONDITION: a. excellent 🕱 b. good 🗆 c. fair 🗆 d. deteriorated 🗀
II. INTEGRITY: a. original site 👿 b. moved 🗆 if so, when?
a list major alterations and dates (if he with)
c. list major alterations and dates (if known):
Gable roof entrance porch added

12. PHOTO: Neg. KK XXII-32, fm. S/SW

13. MAP: NYS DOT composite Patchogue and Sayville Quads





4.71	나는 물병이 많아 되면 하는데 되었다. 그는 것이 되는 그를 말하고 없었다. 그리지는 그리고 얼마나 아내를 하는데 나를 받아 없었다. 그런 말이 되는데 그를 그는데 그를 다니다. 그는데 그를 다니다.				
14.	THREATS TO BUILDING: a, none known b. zoning c. roads c. roads				
15.	RELATED OUTBUILDINGS AND PROPERTY: a. barn				
16.	SURROUNDINGS OF THE BUILDING (check more than one if necessary): a. open land b. woodland c. scattered buildings d. densely built-up e. commercial f. industrial g. residential h. other: see 15 j				
17.	INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: (Indicate if building or structure is in an historic district)				
18.	The Overton House is located on the north side of the street next west of SY 5 opposite the Long Island Rail Road tracks near the Montauk Highway overpass. The residences that surround the house date from a mix of historic periods. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):				
	The Overton House is a $1\frac{1}{2}$ story, rectangular, five bay, center entrance plan, gable roof house with an interior end chimney and five frieze window under the eavegof the principle (south) facade. $6/6$ sash throughout the house.				
<u>SIG</u> 19.	NIFICANCE DATE OF INITIAL CONSTRUCTION: Priot to 1873				
	ARCHITECT:				
	BUILDER:				
20.	HISTORICAL AND ARCHITECTURAL IMPORTANCE:				
	This house was owned by William Overton in 1902 and W. Overton in 1915. It is possible that the owner in 1873 was F. Green.				
	35 Overton Street is a rare survivor of an early house type.				
21.	SOURCES:				
	E. Belcher Hyde. Atlas of the Ocean Shore of Suffolk County, N.Y., (westerly section), 1902. Ibid, 1915.				
2.25	Beers, Comstock. Atlas of Long Island, 1873.				

Research by Society for the Preservation of Long Island Antiquities - KEK